

Tabla de Conversión de Pulgadas a Milímetros

| Pulgadas | | Métrico | Pulgadas | | Métrico | Pulgadas | | Métrico |
|------------|---------------|----------------|--------------|---------------|----------------|--------------|-----------------|----------------|
| Fracción | Decimal | mm | Fracción | Decimal | mm | Fracción | Decimal | mm |
| | 0.0039 | 0.1000 | | 0.5512 | 14.0000 | | 1.8898 | 48.00 |
| | 0.0079 | 0.2000 | 9/16 | 0.5625 | 14.2875 | | 1.9291 | 49.00 |
| | 0.0118 | 0.3000 | | 0.5709 | 14.5000 | | 1.9685 | 50.00 |
| 1/64 | 0.0156 | 0.3969 | 37/64 | 0.5781 | 14.6844 | 2 | 2.0000 | 50.80 |
| | 0.0157 | 0.4000 | | 0.5906 | 15.0000 | | 2.0079 | 51.00 |
| | 0.0197 | 0.5000 | 19/32 | 0.5938 | 15.0813 | | 2.0472 | 52.00 |
| | 0.0236 | 0.6000 | 39/64 | 0.6094 | 15.4781 | | 2.0866 | 53.00 |
| | 0.0276 | 0.7000 | | 0.6102 | 15.5000 | | 2.1260 | 54.00 |
| 1/32 | 0.0313 | 0.7938 | 5/8 | 0.6250 | 15.8750 | | 2.1654 | 55.00 |
| | 0.0315 | 0.8000 | | 0.6299 | 16.0000 | | 2.2047 | 56.00 |
| | 0.0354 | 0.9000 | 41/64 | 0.6406 | 16.2719 | | 2.2441 | 57.00 |
| | 0.0394 | 1.0000 | | 0.6496 | 16.5000 | 2 1/4 | 2.2500 | 57.15 |
| | 0.0433 | 1.1000 | 21/32 | 0.6563 | 16.6688 | | 2.2835 | 58.00 |
| 3/64 | 0.0469 | 1.1906 | | 0.6693 | 17.0000 | | 2.3228 | 59.00 |
| | 0.0472 | 1.2000 | 43/64 | 0.6719 | 17.0656 | | 2.3622 | 60.00 |
| | 0.0512 | 1.3000 | 11/16 | 0.6875 | 17.4625 | | 2.4016 | 61.00 |
| | 0.0551 | 1.4000 | | 0.6890 | 17.5000 | | 2.4409 | 62.00 |
| | 0.0591 | 1.5000 | 45/64 | 0.7031 | 17.8594 | | 2.4803 | 63.00 |
| 1/16 | 0.0625 | 1.5875 | | 0.7087 | 18.0000 | 2 1/2 | 2.5000 | 63.50 |
| | 0.0630 | 1.6000 | 23/32 | 0.7188 | 18.2563 | | 2.5197 | 64.00 |
| | 0.0669 | 1.7000 | | 0.7283 | 18.5000 | | 2.5591 | 65.00 |
| | 0.0709 | 1.8000 | 47/64 | 0.7344 | 18.6531 | | 2.5984 | 66.00 |
| | 0.0748 | 1.9000 | | 0.7480 | 19.0000 | | 2.6378 | 67.00 |
| 5/64 | 0.0781 | 1.9844 | 3/4 | 0.7500 | 19.0500 | | 2.6772 | 68.00 |
| | 0.0787 | 2.0000 | 49/64 | 0.7656 | 19.4469 | | 2.7165 | 69.00 |
| | 0.0827 | 2.1000 | | 0.7677 | 19.5000 | 2 3/4 | 2.7500 | 69.85 |
| | 0.0866 | 2.2000 | 25/32 | 0.7813 | 19.8438 | | 2.7559 | 70.00 |
| | 0.0906 | 2.3000 | | 0.7874 | 20.0000 | | 2.7953 | 71.00 |
| 3/32 | 0.0938 | 2.3813 | 51/64 | 0.7969 | 20.2406 | | 2.8346 | 72.00 |
| | 0.0945 | 2.4000 | | 0.8071 | 20.5000 | | 2.8740 | 73.00 |
| | 0.0984 | 2.5000 | 13/16 | 0.8125 | 20.6375 | | 2.9134 | 74.00 |
| | 0.1094 | 2.7781 | | 0.8268 | 21.0000 | | 2.9528 | 75.00 |
| | 0.1181 | 3.0000 | 53/64 | 0.8281 | 21.0344 | | 2.9921 | 76.00 |
| 1/8 | 0.1250 | 3.1750 | 27/32 | 0.8438 | 21.4313 | 3 | 3.0000 | 76.20 |
| | 0.1378 | 3.5000 | | 0.8465 | 21.5000 | | 3.0315 | 77.00 |
| 9/64 | 0.1406 | 3.5719 | 55/64 | 0.8594 | 21.8281 | | 3.0709 | 78.00 |
| 5/32 | 0.1563 | 3.9688 | | 0.8661 | 22.0000 | | 3.1102 | 79.00 |
| | 0.1575 | 4.0000 | 7/8 | 0.8750 | 22.2250 | | 3.1496 | 80.00 |
| 11/64 | 0.1719 | 4.3656 | | 0.8858 | 22.5000 | | 3.1890 | 81.00 |
| | 0.1772 | 4.5000 | 57/64 | 0.8906 | 22.6219 | | 3.2283 | 82.00 |
| | 0.1875 | 4.7625 | | 0.9055 | 23.0000 | | 3.2677 | 83.00 |
| | 0.1969 | 5.0000 | 29/32 | 0.9063 | 23.0188 | | 3.3071 | 84.00 |
| 13/64 | 0.2031 | 5.1594 | 59/64 | 0.9219 | 23.4156 | | 3.3465 | 85.00 |
| | 0.2165 | 5.5000 | | 0.9252 | 23.5000 | | 3.3858 | 86.00 |
| 7/32 | 0.2188 | 5.5563 | 15/16 | 0.9375 | 23.8125 | | 3.4252 | 87.00 |
| 15/64 | 0.2344 | 5.9531 | | 0.9449 | 24.0000 | | 3.4646 | 88.00 |
| | 0.2362 | 6.0000 | 61/64 | 0.9531 | 24.2094 | 3 1/2 | 3.5000 | 88.90 |
| 1/4 | 0.2500 | 6.3500 | | 0.9646 | 24.5000 | | 3.5039 | 89.00 |
| | 0.2559 | 6.5000 | 31/32 | 0.9688 | 24.6063 | | 3.5433 | 90.00 |
| 17/64 | 0.2656 | 6.7469 | | 0.9843 | 25.0000 | | 3.5827 | 91.00 |
| | 0.2756 | 7.0000 | 63/64 | 0.9844 | 25.0031 | | 3.6220 | 92.00 |
| 9/32 | 0.2813 | 7.1438 | 1 | 1.0000 | 25.40 | | 3.6614 | 93.00 |
| | 0.2953 | 7.5000 | | 1.0039 | 25.50 | | 3.7008 | 94.00 |
| 19/64 | 0.2969 | 7.5406 | | 1.0236 | 26.00 | | 3.7402 | 95.00 |
| 5/16 | 0.3125 | 7.9375 | | 1.0433 | 26.50 | | 3.7795 | 96.00 |
| | 0.3150 | 8.0000 | | 1.0630 | 27.00 | | 3.8189 | 97.00 |
| 21/64 | 0.3281 | 8.3344 | | 1.0827 | 27.50 | | 3.8583 | 98.00 |
| | 0.3346 | 8.5000 | | 1.1024 | 28.00 | | 3.8976 | 99.00 |
| 11/32 | 0.3438 | 8.7313 | | 1.1220 | 28.50 | | 3.9370 | 100.00 |
| | 0.3543 | 9.0000 | | 1.1417 | 29.00 | 4 | 4.0000 | 101.60 |
| 23/64 | 0.3594 | 9.1281 | | 1.1614 | 29.50 | | 4.3307 | 110.00 |
| | 0.3740 | 9.5000 | | 1.1811 | 30.00 | 4 1/2 | 4.5000 | 114.30 |
| 3/8 | 0.3750 | 9.5250 | | 1.2205 | 31.00 | | 4.7244 | 120.00 |
| 25/64 | 0.3906 | 9.9219 | 1 1/4 | 1.2500 | 31.75 | 5 | 5.0000 | 127.00 |
| | 0.3937 | 10.0000 | | 1.2598 | 32.00 | | 5.1181 | 130.00 |
| 13/32 | 0.4063 | 10.3188 | | 1.2992 | 33.00 | | 5.5118 | 140.00 |
| | 0.4134 | 10.5000 | | 1.3386 | 34.00 | | 5.9055 | 150.00 |
| 27/64 | 0.4219 | 10.7156 | | 1.3780 | 35.00 | 6 | 6.0000 | 152.40 |
| | 0.4331 | 11.0000 | | 1.4173 | 36.00 | | 6.2992 | 160.00 |
| 7/16 | 0.4375 | 11.1125 | | 1.4567 | 37.00 | | 6.6929 | 170.00 |
| | 0.4528 | 11.5000 | | 1.4961 | 38.00 | | 7.0866 | 180.00 |
| 29/64 | 0.4531 | 11.5094 | 1 1/2 | 1.5000 | 38.10 | | 7.4803 | 190.00 |
| 15/32 | 0.4688 | 11.9063 | | 1.5354 | 39.00 | | 7.8740 | 200.00 |
| | 0.4724 | 12.0000 | | 1.5748 | 40.00 | 8 | 8.0000 | 203.20 |
| 31/64 | 0.4844 | 12.3031 | | 1.6142 | 41.00 | | 9.8425 | 250.00 |
| | 0.4921 | 12.5000 | | 1.6535 | 42.00 | 10 | 10.0000 | 254.00 |
| 1/2 | 0.5000 | 12.7000 | | 1.6929 | 43.00 | 20 | 20.0000 | 508.00 |
| | 0.5118 | 13.0000 | | 1.7323 | 44.00 | 30 | 30.0000 | 762.00 |
| 33/64 | 0.5156 | 13.0969 | 1 3/4 | 1.7500 | 44.45 | 40 | 40.0000 | 1016.00 |
| 17/32 | 0.5313 | 13.4938 | | 1.7717 | 45.00 | 60 | 60.0000 | 1524.00 |
| | 0.5315 | 13.5000 | | 1.8110 | 46.00 | 80 | 80.0000 | 2032.00 |
| 35/64 | 0.5469 | 13.8906 | | 1.8504 | 47.00 | 100 | 100.0000 | 2540.00 |